

Message

---

**From:** Zachary Griefen [griefen@bnd-law.com]  
**Sent:** 11/14/2022 6:39:17 PM  
**To:** Storm, Linda [Storm.Linda@epa.gov]  
**CC:** Dave Bricklin [bricklin@bnd-law.com]  
**Subject:** (US-95 Thorn Creek to Moscow) FW: US95 day after rain  
**Attachments:** 2022Nov5BtwnCross8&9B.JPG; 2022Nov5BtwnCross8&9A.JPG; 2022Nov5BtwnCross8&9D.JPG

Hi Linda,

Over the weekend, our clients sent us photos of heavy erosion and runoff from ITD's construction activity into WOTUS. Please see below and attached. I'll forward a second email with two additional photos shortly.

Dave Bricklin and I would like to talk with you on the phone. Are you available for a call today at 11:30 AM Pacific?

Thank you,

Zak



Zachary Knox Griefen  
Associate Attorney  
Bricklin & Newman, LLP  
123 NW 36th Street, Suite 205, Seattle, WA 98107  
206.264.8600 | [griefen@bnd-law.com](mailto:griefen@bnd-law.com) | [www.bricklinnewman.com](http://www.bricklinnewman.com)

---

**From:** Stephan Flint <flint.stephan@gmail.com>  
**Sent:** Sunday, November 13, 2022 9:40 PM  
**To:** Zachary Griefen <griefen@bnd-law.com>; Dave Bricklin <bricklin@bnd-law.com>; PRDC Secretary <secretary@paradise-ridge-defense.org>; Al Poplawsky <alpopsky@gmail.com>  
**Subject:** US95 day after rain

Hi Zak and Dave,

There are two undocumented drainages flowing into a pond between Crossings 8 and 9 (different parts of tributary W). These pictures were taken the day after the big rain on Nov 4. "B" shows sediment flowing from a culvert, which was sufficient to bury the hose from a pump ("A" shows buried hose) and dump into adjacent pond "D" which was clean when seen on Oct 30. (Barrel was probably a float to keep hose intake off the pond bottom.) Source of sediment is erosion of highway median; I have pictures of that also.

Steve